



Technical Service Bulletin

Technical Service Bulletin: TSB190194

Released Date: 11-Nov-2019

Image Analyzer Issue in INSITE™ Electronic Service Tool

Image Analyzer Issue in INSITE™ Electronic Service Tool

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.


Contents

Products Affected

- All electronically controlled engine products.

Issue

Work order images created with INSITE™ electronic service tool versions 8.5.0 and 8.5.1 are not able to be properly viewed in ECM Image Analyzer in newer INSITE™ electronic service tool versions. See Figure 1 below for error displayed.



19r99593

Figure 1, ECM Image Analyzer Error Message in INSITE™ Electronic Service Tool.

Resolution

Create a new work order image with the latest version of INSITE™ electronic service tool.

Document History

Date	Details
2019-11-8	Module Created

Last Modified: 11-Nov-2019
