



Technical Service Bulletin: TSB200187

Released Date: 16-Sep-2020

ReCon® Cylinder Head Exhaust Face Visual Differences

ReCon® Cylinder Head Exhaust Face Visual Differences

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- K19
- KTA19G CMEICS K123
- KTA19GC
- KTA19GC CM558
- QSK19 CM2150 MCRS
- QSK19 CM2350 K105
- QSK19 CM500
- QSK19 CM850 MCRS
- QSK19G
- GTA38
- K38
- KTA38GC CM558
- QSK38 CM2150 K106
- QSK38 CM2150 MCRS
- QSK38 CM850 MCRS
- G50
- K50
- K50 DPM
- QSK50 C2150 K107
- QSK50 C2150 MCRS
- QSK50 C2350 K108
- QSK50 C850 MCRS
- QSK50 DF CM850/CM2150 MCRS

Issue

Symptom: Heads may have color difference at the exhaust face.

Resolution

The recon process is salvaging the exhaust face. The parts will have a color difference after finish machining at the exhaust face. This color difference is acceptable.

Description of Change

There is no change in form, fit, and function for these heads.

Customer Communication

There is no change to part number(s). This TSB is to inform the field that parts produced and sold using the machining processes may look visually different but have the same fit, form, and function. See figure in Part Identification section.

Service Parts Availability

Service parts are available.

Table 1, Service Parts

Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
KV Series Cylinder Head Assembly	364632300RX	No	No	NA
	431388700RX	No	No	NA

Part Compatibility

No change to form, fit, and function.

Part Identification



Figure 1, Part Identification

Document History

Date	Details
2020-9-15	Module Created

Last Modified: 16-Sep-2020