



Technical Service Bulletin

Technical Service Bulletin: TSB210029

Released Date: 12-Feb-2021

ReCon® Eliminator™ Filter Visual Differences

ReCon® Eliminator™ Filter Visual Differences

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- G50
- GTA38
- K38
- K50
- K50-DPM
- KTA38GC CM558
- KTAA38 K134G
- QSK38 CM2150 K106
- QSK38 CM2150 MCRS
- QSK38 CM850 MCRS
- QSK38 G CM2358 K122
- QSK45 CM500
- QSK45G
- QSK50 CM2150 K107
- QSK50 CM2150 MCRS
- QSK50 CM2350 K108
- QSK50 CM2350 K130
- QSK50 CM850 MCRS
- QSK50 DF CM850/CM2150 MCRS
- QSK60 CM2150 MCRS
- QSK60 CM2250 K112
- QSK60 CM2350 K116
- QSK60 CM2350 K117
- QSK60 CM2350 K121
- QSK60 CM2350 K133
- QSK60 CM500
- QSK60 CM850 MCRS

- QSK60 G
- QSK60 G CM2358 K110
- QSK78 CM2250 K104
- QSK78 CM2350 K126
- QSK78 CM500

Description of Change

Some ReCon® Eliminator™ filters may be painted. There is no change in form, fit and function for these Eliminator™ filters.

Customer Communication

No change to part number(s), this TSB is to inform field that some ReCon® Eliminator™ filters may look visually different due to paint but have the same form, fit, and function. See Figures 1 and 2 below in Part Identification section.

Service Parts Availability

Service parts are available. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Eliminator™	364947200RX	No	No	-
Eliminator™	537188600RX	No	No	-
Eliminator™	537201700RX	No	No	-
Eliminator™	364946700RX	No	No	-

Part Identification

© Cummins Inc.

© Cummins Inc.



Figure 1, Eliminator™ Without Paint

© Cummins Inc.

© Cummins Inc.



Figure 2, Eliminator™ With Paint.

Document History

Date	Details
2021-2-8	Module Created
2021-2-12	Removed HSK78G.

Last Modified: 12-Feb-2021
