



Technical Service Bulletin: TSB210177

Released Date: 22-Aug-2021

ReCon® Lubricating Oil Pump Engine Assembly Face Visual Difference

ReCon® Lubricating Oil Pump Engine Assembly Face Visual Difference

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- G50
- G50 Natural Gas
- K50
- K50-DPM
- QSK50 CM2150 K107
- QSK50 CM2150 MCRS
- QSK50 CM2350 K108
- QSK50 CM850 MCRS
- QSK50 DF CM850/CM2150 MCRS
- QSK50 CM2150 DEMU
- QSK50 CM2150 K140M
- QSK50 CM2350 K130
- QSK50 CM2350 K146G

Description of Change

Some ReCon® lubricating oil pump engine assembly faces may have a rough surface.


Reason for Change

- The ReCon® process is salvaging the lubricating oil pump body.
- ReCon® lubricating oil pumps will have rough surface on engine assembly face post salvage process. This surface roughness difference is acceptable. This roughness does **not** impact installation of lubricating oil pump and does **not** affect functionality of the lubricating oil pump.

Service Parts Availability

Service parts are available. See Table 1 below for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Lubricating Oil Pump	4294739RX	No	No	-
Part Identification				



Document History

Date	Details
2021-8-13	Module Created