



Technical Service Bulletin

Technical Service Bulletin: TSB230138

Released Date: 25-Jul-2023

New Coolant Thermostat

New Coolant Thermostat

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QSK50 CM2150 MCRS
- QSK60 CM2150 K132M
- QSK60 CM2150 MCRS M
- QSK60 CM2350 K117
- QSK60 CM2350 K121
- QSK60 CM2350 K135
- QSK60 CM2350 K149M

Issue Summary

Symptom:

- Engine shut down due to Fault Code 146 Engine coolant temperature is above the engine protection warning limit.

Root Cause:

- Coolant thermostats are damaged or stuck closed.

Verification

Inspect coolant thermostats for damage. If coolant thermostats are found to be damaged or stuck closed, follow instructions in resolution section.

Resolution

- If coolant thermostats are found to be damaged or stuck closed, replace with new part number in Table 1.
- For coolant thermostat removal and installation instructions, see corresponding Service Manual. Reference Procedure 008-013 in Section 8.

Service Parts

Service parts are offered. See Table 1 for part numbers.

Table 1, Service Parts				
Part Description	Existing Part Number	Obsolete	Superseded	New Part Number
Coolant Thermostat	3629205	No	No	5538724

Document History

Date	Details
2023-7-11	Module Created
2023-7-24	Updated Product Affected.

Last Modified: 25-Jul-2023