



Technical Service Bulletin

Technical Service Bulletin: TSB250220

Released Date: 01-Dec-2025

Inactive Fault Code 173

Inactive Fault Code 173

Warranty Statement

The information in this document has no effect on present warranty coverage or repair practices, nor does it authorize TRP or Campaign actions.

Contents

Product Affected

- QST30 CM552

Issue Summary

Symptom:

- Multiple counts of Fault Code 173 will show as inactive after attempting to start the engine.

Root Cause:

- Some calibrations will activate and deactivate this fault code while attempting to start the engine.

Verification

This issue applies to engines with engine control module (ECM) Codes K50042.XX, K50204.XX or K50220.XX. Connect to the ECM with recommended Cummins® Electronic Service Tool or equivalent and verify the ECM Code.

Resolution

- If Fault Code 173 continually reappears as inactive, this is a nuisance fault code and can be ignored. If Fault Code 173 is showing as active, follow the standard troubleshooting steps.

Document History

Date	Details
2025-11-27	Module Created

Last Modified: 01-Dec-2025
