ALM-4

1. factors affecting corrosion rate :-

- pH :- low pH increases corrosion of steel.
- Temparature :- Higher temparature generally increases the corrosion rate
- Humidity :- High humidity provide moisture & electrolyte, accclarating corrosion
- Oxidizing agents :- Increase the oxidation of steel and can cause rapid corrosion.
- Acid concentration :- Higher concentration of acidic solutions generally cause faster metal attack.

2. Engineering measures :-

- Use corrosion - resistant coatings (or) Linings inside the tanks.
- Select corrosion - resistant materials / alloys where they are required

PDF Image to PDF

- Control temparature, humidity, pH of the operating environment
- Use suitabe corroslon inhibator in the acidic solution.
- Provides the regular inspection, cleaning and maintainance to detect the corrosion early