

Service Case SC-8821 — Resolved

Equipment

ZX-440 serial TF-97220

Symptoms

Pressure fluctuation after sensor replacement. Error E117.

Resolution

Connector was partially seated. Connector reseated; calibration verified; interlock remained enabled throughout. Unit returned to service after validation.

Lesson

Exact error-code retrieval and model applicability were more useful than broad symptom similarity.