

SAHYADRI PETROCHEMICALS LTD.	Doc No: NM-CDU1-2024-067
HSE Dept. — Safety Reporting System	Rev: - Date: 02-Dec-2024
Classification: INTERNAL	Page 1 of 1

NEAR-MISS / INCIDENT REPORT

Hydrocarbon seepage at pump seal — P-1101A

This near-miss was reported by the shift crew of CDU-1 and logged in the facility safety system. It is **not** linked in the system to any maintenance work order or to the condition-monitoring data for P-1101A.

Report No.	NM-CDU1-2024-067	Date / Shift	02-Dec-2024 / Night
Asset	Pump P-1101A	Severity	Near-miss (potential fire)
Reported by	A. Khan (Field Operator)	Area	CDU-1 pump shelter

Description

During the night shift, the operator observed hydrocarbon seepage and light smoke from the P-1101A mechanical seal, approximately three weeks after the November seal replacement. The pump was tripped and standby P-1101B started per SOP-CDU1-1101A. No fire occurred. Area was cordoned and gas-tested.

Immediate Cause / Comment

Recurring seal failure on this pump. The operator noted this is the **fourth seal-related event in 2024** and questioned why the seal keeps failing so soon after replacement. No formal root-cause action was raised.