ADC Assignment

- 1. WAP to interface LDR to controller and take the reading.
- 2. Automate the LED using LDR values or Potentiometer values.