Fire Safety Inspection Report

Fire Safety Inspection Report

Building Name: Sunroof

Inspection Date: 2024-09-30 Inspector Name: Vipul Patil

1. Inspection Summary

This inspection revealed significant fire safety deficiencies within the Sunroof building. The most conce

2. Detailed Findings

Fire Extinguishers:

- Presence: No fire extinguishers were found on the premises.
- Condition: N/A (No fire extinguishers present)
- Comments: The absence of fire extinguishers is a major safety concern. This lack of readily available

Fire Alarm System:

- Condition: Partially functional
- Comments: The fire alarm system is not fully operational. It is not present on the second floor and so

Exits:

- Number: 2
- Condition: N/A (No specific information provided on the condition of the exits)
- Comments: While the presence of two exits is positive, further information is required about their con-

3. Risk Assessment

The lack of fire extinguishers, the partially functional fire alarm system, and the outdated system lacking

4. Next Steps

The following steps are crucial to address the identified fire safety deficiencies and mitigate the risks:

Fire Safety Inspection Report

- Immediate Action:
 - Install Fire Extinguishers: Immediately install a sufficient number of fire extinguishers in easily acce
 - Repair Fire Alarm System: Immediately repair the existing fire alarm system to ensure full functional
 - Replace Outdated System: Replace the outdated fire alarm system with a modern system that mee
 - Assess Exit Conditions: Thoroughly assess the condition and accessibility of all exits to ensure the
- Long-Term Solutions:
 - Develop Fire Safety Plan: Create a comprehensive fire safety plan that includes evacuation proced
 - Regular Inspections: Implement a regular schedule for fire safety inspections to ensure ongoing co
 - Employee Training: Provide fire safety training to all building occupants, covering topics such as fir

Recommendations:

- It is strongly recommended that a qualified fire safety professional be consulted to conduct a thorough
- The building owner/manager should prioritize the implementation of the above recommendations to en