CALIFORNIA HIGHWAY PATROL (CHP)
STATE OF CALIFORNIA • TRAFFIC COLLISION REPORT (CHP 555)

COLLISION REPORT #
CHP-2026-881290

Area Office: San Jose Area Office (Coast Division - 725)

Crash Date & Time: 10/18/2026 at 23:42 Hours (11:42 PM)

COLLISION LOCATION & DISPATCH TIMELINE

Jurisdiction: State Route 85 Northbound	**Mile Marker: Post Mile 12.4 (Near Saratoga Ave)**	**City / County:** San Jose / Santa Clara
CAD Call Received: 23:42 Hours	**Officer Dispatched:** 23:44 Hours	**Officer On Scene: 23:51 Hours**
Road Surface: Asphalt (Dry)	**Lighting:** Dark / No highway streetlights	**Collision Type:** Solo Vehicle Guardrail Impact

PARTY & VEHICLE IDENTIFICATION (PHYSICAL ROADSIDE INSPECTION)

Party 1 (Driver / Registered Owner)	Vehicle Description & Physical Markings
Driver: Mark T. Henderson (DOB: 08/19/1982) **License:** CA • F9824102 **Address:** 842 Saratoga Ave, Apt 14, San Jose, CA **Insurance Card:** Pacific Horizon Mutual (PA-672109-04) **Sobriety / Impairment:** HGN evaluated; negative for alcohol. Agitated demeanor. **Medical Transport:** Evaluated on scene by AMR; signed refusal.	**Year / Make / Model:** 2003 Toyota Celica Coupe (Silver) **Plate Displayed:** CA • 6TRK814 (Rear plate mounted) **Physical VIN Inspected (Door Jamb Rivet):** **JT2DD32T430199411** *(Note: Officer noted discrepancy against dashboard sticker scratch)* **Primary Damage:** **Front Left (Driver-side) crush** **Vehicle Disposition:** Towed from scene by Coastside Towing.

INVESTIGATING OFFICER FACTUAL SUMMARY

On 10/18/2026 at 23:42 hours, CHP Communications broadcast a solo-vehicle collision on NB SR-85 just south of Saratoga Avenue. Upon my arrival at 23:51 hours, I observed a silver 2003 Toyota Celica (CA plate 6TRK814) disabled against the west metal W-beam guardrail in the center median. The vehicle displayed heavy impact crush damage concentrated on the FRONT LEFT (driver-side) quarter. The front bumper cover was torn and separated from the driver-side frame horn, the hood was crumpled and buckled upwards towards the windshield, the driver-side composite headlamp assembly was shattered, and the left front wheel assembly was forced backward into the wheel well with significant negative camber. Driver Henderson was outside the vehicle on the median shoulder. Henderson stated he was driving home and claimed an unknown phantom pickup truck swerved into his lane, causing him to lose control and strike the median guardrail. Physical evidence at scene: 42 feet of tire scrub marks on the asphalt traveling from the #1 lane into the center median guardrail. Fresh metal scrape and paint transfer on three consecutive guardrail posts matching the silver Celica front-left bumper height. Officer inspected the driver door B-pillar federal certification label and recorded VIN JT2DD32T430199411. Vehicle was deemed unroadworthy and impounded/towed by rotational contract tow.

Investigating Officer: Officer D. Alvarez #18442	**Reviewing Sergeant:** Sgt. K. Peterson #12014	**Report Date:** 10/19/2026