Metallurgical Engineering

1.	Which	of the following heat treatment creates a case hardened surface?	
	a.	Flame hardening	
	b.	Carburizing	
	c.	Nitriding	
	d.	Cyaniding	
2.	The breaking stress of a particular steel is 1.5 GPa. What force will be needed to break a p		
	wire of	f diameter 1 mm?	
	a.	1178 N	
	b.	1195 N	
	c.	1170 N	
	d.	1180 N	
3.	Which of the following elements in steel can enhance the machinability by increasing sulphur content?		
	a.	Aluminium	
	b.	Manganese	
	c.	Copper	
	d.	Calcium	
4	Flavos i		
4.	FIdWS	n conductive material can be detected by	
	a.	Radiography	
	b.	Holography	
	C.	Eddy current testing	
		Ultrasonic testing	
5		of the following methods is used to determine the atomic and/or magnetic structure of a	
	materi	al?	
	a.	Scanning electron microscopy	
	b.	Transmission electron microscopy	
	c.	X-ray diffraction	

d.	Optical microscopy
e.	Neutron diffraction
6.Which	of the following mills is not used for fine grinding of ores?
a.	Ball mill
h	Turbo mill

- b. Turbo mill
- c. Vibrating mill
- d. Hammer mill
- 7. Which of the following laws states that the vapor pressure of an ideal solution is proportional to the mole fraction of solvent?
 - a. Henry's law
 - b. Sievert's law
 - c. Raoult's law
 - d. Gibbs-Duhem equation
- 8. Why are low alloy steels welded using nickel alloys as filler metals?
 - a. For controlling hot cracking
 - b. For controlling cold cracking
 - c. For controlling porosity
 - d. For controlling distortion
- 9. Which of the following metal working processes is not a hot working process?
 - a. Rolling
 - b. Forging
 - c. Extrusion
 - d. Wire drawing