## **SERVICE CALL REPORT - Exception Report** Head Office: 10th Floor, Presige Centre Court, Office Block, Vijaya Forum Mall, 183, N.S.K Salai, Vadapalani, Chennai, Tamilnadu-600026 Customer Support Number - 0484 3103266 / 0484 4723266 : Support email id : customer.care@numericups.com CUSTOMER NAME & ADDRESS: SERVICE CALL REPORT NO: SA-4451090 STATE BANK OF INDIA, HAAT BAJAR MAU ROAD MEHGAON DISTI BHIND, MADHYA PRADESH DATE: 22.11.2024 Amayan - 477557 India AMC PO NO: SERVICE BRANCH NAME: BHOPAL SITE / ATM ID NO: NA / S1BW003512046 SERVICE BRANCH CONTACT NO: 0755-2764201/2764202 SERVICE BRANCH EMAIL ID: purushottam.dwivedi-02@numericups.com CONTACT PERSON NAME: Mr.Sandeep Yadav TELEPHONE/ MOBILE NO: 9131785304 SITE CATEGORY: B Call Received on: 21.11.2024: 15:41:23 Call Registration No: 04562228 Call Assigned on: 22.11.2024 : 10:34:37 Visit Attended on: 22.11.2024 : 10:48:38 Visit Completed on: 22.11.2024 : 12:39:23 Customer Category: UPS TECHNOLOGY: DIGITAL HP TYPE OF CALLS: Breakdown - 1PH UPS BD UPS TYPE: 1P1 Customer Status: CAMC Call Type: Minor PRODUCT DETAILS - U9DHP2KVA96/11UNI/SNMP/EPS120/1SET DC VOLTS: 96 UPS SI.No: IX084006237 UPS CONFIGURATION: UNI UPS KVA: 02 **BATT AH:** 100 BATT VOLTS: 12V No OF SETS: NA Batt Batch No: ID4HS04403623617, ID4HS04403623680, ID4HS04403623620, ID4HS04403623613 BATT TYPE: TUBULAR **BATT MAKE: SOUTHERN PF** ID4HS04403623585, ID4HS04403623586, ID4HS04403623589, ID4HS04403623596 SERVO STABILIZER / ISOLATION SI.No PRODUCT DETAILS - Captured by site - engineer during site visit - U9DHP2KVA96/11UNI/SNMP/EPS120/1SET **UPS KVA:** 02 DC VOLTS: 96 UPS SI.No: IX084006237 UPS CONFIGURATION: UNI **BATT AH:** 100 **BATT VOLTS**: 12V BATT QTY: 8 No OF SETS : NA Batt Batch No: ID4HS04403623617, ID4HS04403623680, ID4HS04403623620, ID4HS04403623613 ID4HS04403623585, ID4HS04403623586, ID4HS04403623589, ID4HS04403623596 BATT MAKE: SOUTHERN PP BATT TYPE: TUBULAR **SERVO STABILIZER / ISOLATION** KVA: PROBLEM REPORTED BY CUSTOMER: Backup Issue ROOT CAUSE OF FAILURE (ENGINEERS OBSERVATION): Battery Related FRONT PANEL INDICATION: BATT LOW PROBLEM OBSERVED IN WHICH MODE: Others (Yes) ACTION TAKEN: Check and found UPS working ok CONCLUSION OF FAILURE: Others Backup Issue ( Check and found UPS working ok with load but not providing backup due to 04 no. Battery weak/faulty. Kindly arrange to replace 04 no. faulty battery at Spare parts replaced, if any: (Material code details are given in the front wrapper)

ACTUAL SPARE PARTS FAILED DETAILS					ACTUAL SPARE PARTS REPLACED DETAILS								
SAP CODE			DI	DESCRIPTION		Υ	SAP CODE			DESCRIPTION		Υ	
NA			NA			4	N.	A		NA	N		
UPS PARAMETERS				BATT PARAMERTERS			SITE PARAMETERS			GENERAL INFORMATION REG SITE			
PARAMETERS	R	Υ	В	DC Volts W/O Battery	109	Neutral to Earth Voltage	2	Static bypass function test			Yes		
EB I/P Volts w.r.t Neutral	235			DC Volts with Battery	105	Power Failure Duration / Day	2	Communication / Remote pannel			Yes		
EB I/P Current	15			DC Volts W/O Mains	101	No of time Power Failure / Day	4	Tightness of all the termination			Yes		
EB I/P Volts - Ph to Ph				Batt Charging Current		10	Input power variation	0	Appearance of the Battery			Yes	
Bypass Voltage w.r.t Neutral	235			Battery Condition - OK qty		4	Gen set availability	No	Input / Output break status			ОК	
UPS O/P Volts w.r.t Neutral	230			Battery Condition - weak qty		4	Dedicated Earth availability	Yes	Input / Output cable status			ОК	
UPS O/P Volts - Ph to Ph				Distilled water level		None	Room Temperature	32	Fan rotation			Yes	
UPS O/P Current	2			DC Low Cut off Volts		85	Air Conditioner/Room Ventilation			cleaning		Yes	
Type of Load IT Loads No of Parallel bank					0	Input frequency	Remarks : Check and found UPS working ok with load but not backup due to 04 no. Battery weak/faulty. Kindly arrange to repfaulty battery at earliest.						
JPS SYSTEM PRESENT STATUS: Working Satisfactorily						If PCB call-Approval status :							

Numeric Engineer's Remarks / Suggestion : Check and found UPS working ok with load but not providing backup due to 04 no. Battery weak/faulty. Kindly arrange to replace 04 no. faulty battery at earliest.

The reported call has been completed and UPS is working satisfactorily on load, Preventive Maintenance carried out.

EMP Code : 3245780

Customer Email id : sandeep1.yadav@hitachi-payments.com

Customer signature: Signed By: Mr.Sandeep Yadav

Customer Email id . sandeepr.yadav@macmi-payments.co

Signature :

Signed By: Chandrabhooshan Sharma Name & Designation : CHANDRABHOOSAN SHARMA & Technician

Payments can be made by the way of Demand Draft/RTGS and favouring NOVATEUR ELECTRICAL & DIGITAL SYSTEMS PRIVATE LIMITED. Cash mode of payment is not acceptable. For RTGS, Bank details are as follows - Bank A/C No. '0908810469600130, BNP PARIBAS', Chennai; RTGS / IFSC code:BNPA0009088.

NPDM/SER/FR/01/Rev 12

Back-up test												
		Serial Number.	Health Check Status	SP.GR. only Tubular Batt.	Individual Battery volts during charger ON	Individual Battery Voltages at regular interval while discharging						
	BATTERY Batch No.					I	II	III	IV	٧	VI	
						10 minutes	20 minutes	30 minutes	40 minutes	50 minutes	60 minutes	
1	ID4HS04403623617	1130880	Weak		13.5	11.50	10.00					
2	ID4HS04403623680	1130881	Weak		13.5	11.80	10.20					
3	ID4HS04403623620	1130882	Weak		13.5	11.90	10.40					
4	ID4HS04403623613	1130883	Weak		13.5	11.95	10.40					
5	ID4HS04403623585	1130884	Good		13.5	12.28	11.90					
6	ID4HS04403623586	1130885	Good		13.5	12.30	11.80					
7	ID4HS04403623589	1130886	Good		13.5	12.50	11.90					
8	ID4HS04403623596	1130887	Good		13.5	12.60	12.10					
TOTAL	DC VOLTAGE	108.0										