


No. HQ/EN/Track/RRM/CS/3/28550

Date: 19.09.2025

The CGMs
EDFC & WDFC

Sub: - Correction Slip No. 03 dt. 17.09.2025 to the DFC Railroad Manual 2024.

Competent Authority has decided that Correction/addition as indicated in the enclosed Correction Slip no. 03 dated 17.09.2025, to relevant para (New Para 748) of DFC Railroad Manual-2024 be made.


(Saurabh Singh Patel)
GGM/Bridge

Copy to:

- (1) Dir/PP & Dir/Infra for kind information please.
- (2) ED/AM for kind information please.
- (3) GGM/Tech for kind information please.
- (4) Principal/HHI for kind information please.

DFC Railroad Manual (July-2024)

Addendum & Corrigendum Slip No.3 dt.17.09.2025

New Para 748 – Action in case of reporting of unusual occurrence (including Jerk Message)

Following action to be taken:

- (1) The IMSD In charge or any other Executive/P-way shall proceed as quickly as possible to site, inspect the length of track reported and check the track for any abnormality etc. If nothing is found at reported location, or in the vicinity, he shall exercise check for 1 km track length i.e. 500 m on both sides of reported location. There after he shall attend the track if defect is found and allow the trains at the speed for which condition of track is considered fit. Full sectional speed may be allowed, if he is sure that there are no defects in track.
- (2) When IMSD In charge or any other Executive/P-way cannot find the cause of jerk and visibility is very low (i.e. during night) he may even impose speed restriction of 30 kmph or less on the suspected location. The site will then again be inspected by Executive/P-way after sunrise. After getting satisfied with the condition of track he may remove/modify the restriction imposed.
- (3) IMSD In charge or any other Executive/P-way shall submit a detailed report to the IMD In charge.
- (4) Whenever possible, the IMD In charge should personally examine the track reported on for defects.



-----*****-----