


No. HQ/EN/Track/RRM/CS/5/28550

Date: 08.12.2025

The CGMs
EDFC & WDFC

Sub: Correction Slip No. 05 dt. 02.12.2025 to the DFC Railroad Manual-2024

Competent Authority has decided that Correction/addition as indicated in the enclosed Correction Slip no. 05 dated 02.12.2025, to relevant para of DFC Railroad Manual-2024 be made.


(Arun Kumar Tiwari)
GGM/Tech

Copy to:

- (1) Dir/PP and Dir/Infra for kind information, please.
- (2) ED/AM, ED/Infra, ED/Projects and ED/CM for kind information, please.
- (3) GGM/Bridge for kind information, please.
- (4) Principal/HHI for kind information, please.

DFC Railroad Manual (July-2024)

Addendum & Corrigendum Slip No.5 dated 02.12.2025

Para 836(b)(i)(1) :

Maintenance of Switch Assembly: The existing Para 836(b)(i)(1) shall be modified and read as under:

Para 836(b)(i)(1):

It is chipped / cracked over small lengths aggregating to 200 mm within a distance of 1000 mm from ATS in case of 1 in 8.5 switches and within a distance of 2000 mm from ATS in case of 1 in 12 switches. Chipped length will be the portion where tongue rail has worn out for a depth of more than 10 mm over a continuous length of 10 mm. (The tongue rail can, however, be reused after reconditioning of the broken/worn/damaged tip by welding)

-----*****-----

AB
8/12/25