



LASER EXPERTS INDIA LLP

27/3 ANUMEPALLI
BEGAPALLI ROAD , ZUZUVADI
HOSUR 635126
TAMIL NADU 33
PAN NO AAGFL9943F
GSTIN 33AAGFL9943F1Z6
UDYAM-TN-11-0000905

SERVICE REPORT

Report ID: REP-CDB09DA7

Date of Issue: 30/06/2026

Track ID: FSR-2026-00009

CUSTOMER INFORMATION

Company: NILKAMAL CONTROL SYSTEMS PRIVATE LIMITED(PUNE)
Contact: NILKAMAL CONTROL SYSTEMS PRIVATE LIMITED(PUNE)
Mobile: 8605016954

EQUIPMENT SPECIFICATIONS

Brand / Maker: Raycus
Model: sdsf
Serial No: fssf
Power Rating: 3kW

DIAGNOSTICS & FINDINGS

Customer Complaint: okokok

Fault Found: Burned optical collimator lens and degraded pump diode modules.

Root Cause Analysis: Water chiller failure caused heat accumulation on QBH connector.

REPAIR ACTIONS PERFORMED

Replaced collimator lens assembly and Raycus pump diodes. Re-aligned optical path.

SPARE PARTS REPLACED

- Laser Module (IPG 1kW) (Qty: 1)
- Control Board V3.2 (Qty: 1)

MANDATORY VALIDATION TESTS

1. Output Power Test: PASS - Stable 3.02kW output
2. Stability Test: PASS - Less than 1% variance over 2 hours
3. Burn-In Test: PASS - 4 hour burn-in validation completed
4. Alarm Verification: PASS - Interlocks and back-reflection alarms clear
5. Temperature Test: PASS - Max module temp 24.5C
6. Communication Test: PASS - RS232 and EtherCAT state operational

FINAL TESTING OUTCOME: PASS

Engineer In-Charge: System Administrator

Authorized Quality Control Signoff