

Site Standard - Grinding Mill Isolation and Entry

Doc No. **RB-4410-SG-005** Rev 3

- Isolate the GMD at the 33 kV feeder and the cycloconverter; verify zero energy by attempted start.
- Isolate lube and hydrostatic lift systems; bleed PT-3104 to zero.
- Chock the mill shell before any person enters; inching drive is locked out during entry.
- Confined-space entry permit and gas test required (no CS2 source expected, but flotation area is adjacent).
- Liner handler operation requires a dedicated spotter and exclusion zone.