
Problems:

1.



The output of accumulator (ou) is not a ramp.

2.

For the 1st multiplier, there are two output during the flagout gap. The reason is: I didn't synchronize the multiplier with flag out from NCO.

