

31	
6 ××× 38	

STUB
TO USE WHEN IN
OPERATION
MORE
(To protect

MORE
(To protect
pszyo1 from
ESD or any
other Burning)

	R1	R2	R3	Uin
Manual	NA	NIA	N/A	5V
PROGRAM	Ole	Ok	Ok	OV
G113K5	1.5 k	1.5k	1.5k	2.5V
G294K6	3.3 K	3.3k	6.8k	
H1 J3 L9	6,8k	6.8k	1-210	
G2 13 L5	1.5k	OK	13.5	

(Instead 6.8k we can use 4.5k (measure it!) &