

Final pressure after all screws are tightened
High
Compressive Pressure
Low