


# 01 Pi 5 boot + serial capture

Wiring sheet for the official Raspberry Pi Debug Probe

**STOP POINT: keep Pi USB-C power unplugged until capture is ready.**

## CONNECT THESE TWO CABLES



Use the supplied UART cable with a small white 3-pin plug at each end. Match the keyed plugs gently. Use U / UART on the probe; leave D unused.

## FIND THE PI CONNECTOR

The small connector labelled UART is between the two micro-HDMI ports.



Location guide only - not a scaled board drawing.

## WHAT THE THREE WIRES CARRY

Logical signals only; this is not connector pin order or cable colour coding.



## CHECK BEFORE WE CONTINUE

- ☐ Pi and probe were unpowered when the UART cable was fitted.
- ☐ Probe U / UART connects to the Pi dedicated UART socket.
- ☐ Probe USB connects to the computer; Pi USB-C power stays unplugged.
- ☐ Shrike, logic analyzer and motors remain disconnected.

**NEXT: identify the serial port and verify the boot SD card, then start capture.**

Expected console setting: 115200 baud, 8 data bits, no parity, 1 stop bit.

Sources / verified 2026-09-09

[Raspberry Pi: Debug Probe connections](#)

[Raspberry Pi: Pi 5 dedicated UART10 header](#)

AxiomOS console: `kernel/src/arch/aarch64/platform/rpi5/uart.rs @ 34fe92c`