

RO Number:

Inspection Number: 2949481

Year: 2019

Insurance:

Make: Chevrolet

Model: Trax LS FWD

VIN: 3GNCJKSBXKL343951

Estimator: Hite, Nathaniel

IMPORTANT! Please validate vehicle is equipped with listed ADAS system components by performing a visual inspection!

Scanning Requirements

PRE AND POST SCANS REQUIRED

<https://www.gmparts.com/content/dam/gmparts/na/us/en/index/technical-resources/position-statements/02-pdfs/new/pre-post-scan-collision-vehicles.pdf>

General Motors takes the position that all vehicles being assessed for collision damage repairs must be tested for Diagnostic Trouble Codes (DTCs) during the repair estimation in order to identify the required repairs. Additionally, the vehicle must be retested after all repairs are complete in order to verify that the faults have been repaired and new faults have not been introduced during the course of repairs.

Identified ADAS Related Services to be Performed

Based on the estimate, the following calibrations/initializations have been identified:

Seat Belt Inspection (1)

Steering Angle Sensor (1)

Recommendations

OPUS recommends a pre-scan on this vehicle. To determine what type of scan should be performed, refer to service information and certification requirements.

Calibrations

<u>ADAS System/Components</u>	<u>Location</u>	<u>Calibration</u>
Seat Belt Inspection		
Seat Belt	Interior	Seat Belt Inspection

Seatbelts must be inspected after a collision to ensure passenger safety even if the airbags have not deployed.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=2949481&adasChecklistMatrixVehicle=4406&type=1&model=Trax LS FWD)

[adasInspection=2949481&adasChecklistMatrixVehicle=4406&type=1&model=Trax LS FWD](https://opusadas.z13.web.core.windows.net/links?adasInspection=2949481&adasChecklistMatrixVehicle=4406&type=1&model=Trax LS FWD)

Steering Angle Sensor

Steering Angle Sensor	Column	Steering Angle Sensor
-----------------------	--------	-----------------------

Chevrolet states that whenever any of the following services or events occur, a steering angle sensor calibration must be performed:

- Steering column removal or replacement
- Wheel alignment
- Steering gear replacement
- Collision or other physical damage (see note below)

- Power steering control module replacement
- Electronic brake control module replacement
- Steering angle sensor replacement

NOTE: GM defines the collision or other physical damages as exceeding minor outer body panel distortion without an airbag deployment. See service information for the post collision steering column inspection procedure before the SAS centering is carried out.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=2949481&adasChecklistMatrixVehicle=3234&type=1&model=Trax LS FWD)

[adasInspection=2949481&adasChecklistMatrixVehicle=3234&type=1&model=Trax LS FWD](https://opusadas.z13.web.core.windows.net/links?adasInspection=2949481&adasChecklistMatrixVehicle=3234&type=1&model=Trax LS FWD)

Identified ADAS Systems

<u>System</u>	<u>Component</u>	<u>Location</u>
Seat Belt Inspection	Seat Belt	Interior
Steering Angle Sensor	Steering Angle Sensor	Column

The Fine Print:

The Fine Print (Legaleze)

The ADAS MAP™ report is for informational purposes only and should not be considered as a replacement for Original Equipment Manufacturers (OEM) diagnostic, repair or calibration recommendations and procedures. The ADAS MAP™ platform utilizes data from multiple sources such as VIN, ADAS and safety system build data. While this data is considered accurate, Auto Techcelerators, LLC. makes no guarantees about its accuracy or completeness because it is being generated and delivered by third-parties.