

RO Number: 853631

Inspection Number: 3311763

Year: 2024
Make: Honda
Model: HR-V Sport AWD w/Continuously Variable
Transmissio
VIN: 3CZRZ2H52RM758869

Insurance:

Estimator: Livingood-strauss, Kayla

IMPORTANT! Please validate vehicle is equipped with listed ADAS system components by performing a visual inspection!

Scanning Requirements

Pre & Post Scan Requirements

<https://techinfo.honda.com/rjanisis/pubs/web/ASP04485.pdf>

It is the position of American Honda that all vehicles* involved in a collision† must have the following minimum diagnostic scans, inspections, and/or calibrations done to avoid improper repair: A preliminary diagnostic scan during the repair estimation phase to determine what diagnostic trouble codes (DTCs) may be present, so proper repairs may be included. (See "Background on Scan Requirements" on PDF for more information. A post-repair diagnostic scan to confirm that no DTCs remain. Any repair that requires disconnection of electrical components in order to perform the repair will require a post-repair diagnostic scan to confirm if the component is reconnected properly and functioning. Damage that requires the replacement of body parts will always require a post-repair diagnostic scan.

Identified ADAS Related Services to be Performed

Based on the estimate, the following calibrations/initializations have been identified:

ADAS L3: Static Calibration - A (1)
Seat Belt Inspection (1)
Seat Related Calibration (1)
Steering Angle Sensor (1)

Recommendations

OPUS recommends a pre-scan on this vehicle. To determine what type of scan should be performed, refer to service information and certification requirements.

OPUS recommends utilizing OEM software to perform a post-scan on this vehicle.

Calibrations

<u>ADAS System/Components</u>	<u>Location</u>	<u>Calibration</u>
Lane Departure / Keep Systems		
Multipurpose Camera	Windshield	ADAS L3: Static Calibration - A

Aim the Multipurpose Camera if:

- There is an SRS deployment
- Diagnostic Trouble Code (DTC) stating misalignment/error (follow diagnostic procedures first)
- Structural damage beyond minor cosmetic abrasions to any of the welded, riveted panels, or bonded parts of the main unibody
- Beyond minor cosmetic abrasions damage to the bolt-on front bulkheads, front or rear bumper impact bars, or door intrusion beams.

Any of the following is removed, installed, replaced, or adjusted:

- Windshield
- Multipurpose Camera NOTE: Honda requires OEM Glass

ADAS targets are optional for system calibration; there is a dynamic calibration option.

Before calibrations occurs, the vehicle requires:

- Full tank of fuel
- Correct tire sizes and pressures
- Unmodified suspension
- No excessive weight in the trunk of the vehicle

NOTE: A four wheel alignment is required if suspected to be out of spec or after a collision repair, but camera aiming is not required in the event a four wheel alignment is performed.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3311763&adasChecklistMatrixVehicle=3187&type=1&model=HR-V Sport AWD w/Continuously Variable Transmisio)

[adasInspection=3311763&adasChecklistMatrixVehicle=3187&type=1&model=HR-V Sport AWD w/Continuously Variable Transmisio](https://opusadas.z13.web.core.windows.net/links?adasInspection=3311763&adasChecklistMatrixVehicle=3187&type=1&model=HR-V Sport AWD w/Continuously Variable Transmisio)

Occupant Detection

Occupant Classification System

Passenger Seat

Seat Related Calibration

Honda states that after any collision and regardless of damage, that a "Passenger Seat Weight Output Check" must be performed. The passenger seat must be empty and upright in a middle of track position when performing the check. If the passenger seat is removed for any reason the same check must be performed.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3311763&adasChecklistMatrixVehicle=4375&type=1&model=HR-V Sport AWD w/Continuously Variable Transmisio)

[adasInspection=3311763&adasChecklistMatrixVehicle=4375&type=1&model=HR-V Sport AWD w/Continuously Variable Transmisio](https://opusadas.z13.web.core.windows.net/links?adasInspection=3311763&adasChecklistMatrixVehicle=4375&type=1&model=HR-V Sport AWD w/Continuously Variable Transmisio)

Seat Belt Inspection

Seat Belt

Interior

Seat Belt Inspection

The seat belt system needs to be checked and components potentially replaced after any collision that results in the deployment of seat belt tensioners or airbags, or after moderate to severe collisions. Always inspect for physical damage, check for system errors with a scan tool, and ensure all components are functioning correctly before returning the vehicle to service.

Seatbelts must be inspected after a collision to ensure passenger safety even if the airbags have not deployed.

Note: The deployment record should be checked with a scan tool to verify there are no deployments. Honda vehicles will sometimes not set fault codes to indicate deployments, this data should be investigated within the Honda Deployment Record.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3311763&adasChecklistMatrixVehicle=4413&type=1&model=HR-V Sport AWD w/Continuously Variable Transmisio)

[adasInspection=3311763&adasChecklistMatrixVehicle=4413&type=1&model=HR-V Sport AWD w/Continuously Variable Transmisio](https://opusadas.z13.web.core.windows.net/links?adasInspection=3311763&adasChecklistMatrixVehicle=4413&type=1&model=HR-V Sport AWD w/Continuously Variable Transmisio)

Steering Angle Sensor

Steering Angle Sensor

Column

Steering Angle Sensor

Honda states that upon a battery disconnect, alignment, column removal and replacement, or clockspring replacement that the steering angle sensor calibration referred to as Neutral Position Learning must be performed. In some newer models this will need to be performed first in ABS/VSA module and then completed within the EPS (Electronic Power Steering) module (if fitted).

OEM Reference:[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3311763&adasChecklistMatrixVehicle=5092&type=1&model=HR-V Sport AWD w/Continuously Variable Transmissio)[adasInspection=3311763&adasChecklistMatrixVehicle=5092&type=1&model=HR-V Sport AWD w/Continuously Variable Transmissio](https://opusadas.z13.web.core.windows.net/links?adasInspection=3311763&adasChecklistMatrixVehicle=5092&type=1&model=HR-V Sport AWD w/Continuously Variable Transmissio)**Identified ADAS Systems**

<u>System</u>	<u>Component</u>	<u>Location</u>
Blind Spot Monitoring Systems	Blind Spot Radar	Rear Quarter Panels
Lane Departure / Keep Systems	Multipurpose Camera	Windshield
Occupant Detection	Occupant Classification System	Passenger Seat
Seat Belt Inspection	Seat Belt	Interior
Steering Angle Sensor	Steering Angle Sensor	Column

The Fine Print:**The Fine Print (Legaleze)**

The ADAS MAP™ report is for informational purposes only and should not be considered as a replacement for Original Equipment Manufacturers (OEM) diagnostic, repair or calibration recommendations and procedures. The ADAS MAP™ platform utilizes data from multiple sources such as VIN, ADAS and safety system build data. While this data is considered accurate, Auto Techcelerators, LLC. makes no guarantees about its accuracy or completeness because it is being generated and delivered by third-parties.