



North Star Moon Twp
5854 University Blvd
Moon Twp, PA 15108

RO Number: 3802

Inspection Number: 3123749

Year: 2023

Insurance: ALLSTATE PROPERTY AND CASUALTY
INSURANCE COMPANY

Make: Subaru

Model: Forester Wilderness w/Continuously Variable

Transm

VIN: JF2SKAMC8PH492268

Estimator: Shulln, CJ

IMPORTANT! Please validate vehicle is equipped with listed ADAS system components by performing a visual inspection!

Scanning Requirements

PRE AND POST SCANS REQUIRED

https://oem1stop.com/sites/default/files/Subaru_Pos_Pre-and-Post-Scan_Revised%288-7-20%29.pdf

For Subaru vehicles from model year 2004 and forward involved in a collision, Subaru collision repair procedure requires that pre-repair scanning be performed. Pre-scanning will reveal DTCs for items that are not functioning properly in the vehicle. It allows a shop to identify any issues early in the estimate process, allowing a more complete estimate and encompassing repair process. Additionally, Subaru collision repair procedure also requires that post-repair scanning be performed on these vehicles. Post-scanning is critical in ensuring the malfunctioning items have been repaired and there are no remaining DTCs. It may also assist in assuring the appropriate calibrations and reinitializations have been performed.

Identified ADAS Related Services to be Performed

Based on the estimate, the following calibrations/initializations have been identified:

ADAS L3: Static - B & ADAS L2: Dynamic Calibration (1)

ADAS L3: Static Calibration - B (1)

Seat Related Calibration (1)

ADAS L1: Initialization / Programming (1)

Seat Belt Inspection (1)

Recommendations

OPUS recommends a pre-scan on this vehicle. To determine what type of scan should be performed, refer to service information and certification requirements.

OPUS recommends utilizing OEM software to perform a post-scan on this vehicle.

Calibrations

<u>ADAS System/Components</u>	<u>Location</u>	<u>Calibration</u>
Adaptive Cruise Control		
Eyesight Stereo Camera	Windshield	ADAS L3: Static - B & ADAS L2: Dynamic Calibration

Calibrate Eyesight Camera System if any of the following occur:

- Windshield, headliner, overhead console, or stereo camera is removed, installed, replaced, adjusted, or repaired.
- Vehicle was involved in a collision exceeding cosmetic body panel distortion.



North Star Moon Twp
5854 University Blvd
Moon Twp, PA 15108

installed, or replaced. Special tools are required for system check. ADAS targets are not required for system calibration. NOTE: A scan tool is not required for this procedure.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3123749&adasChecklistMatrixVehicle=861&type=1&model=Forester Wilderness w/Continuously Variable Transm)

[adasInspection=3123749&adasChecklistMatrixVehicle=861&type=1&model=Forester Wilderness w/Continuously Variable Transm](https://opusadas.z13.web.core.windows.net/links?adasInspection=3123749&adasChecklistMatrixVehicle=861&type=1&model=Forester Wilderness w/Continuously Variable Transm)

Seat Belt Inspection

Seat Belt

Interior

Seat Belt Inspection

Seatbelts must be inspected after a collision to ensure passenger safety. While ADASMap and Alldata serve as valuable resources to assist in the repair process, it is ultimately the responsibility of the repair professional to follow proper procedures and safety guidelines. For the most accurate and up-to-date information, always consult the vehicle manufacturer's service manual when available.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3123749&adasChecklistMatrixVehicle=4432&type=1&model=Forester Wilderness w/Continuously Variable Transm)

[adasInspection=3123749&adasChecklistMatrixVehicle=4432&type=1&model=Forester Wilderness w/Continuously Variable Transm](https://opusadas.z13.web.core.windows.net/links?adasInspection=3123749&adasChecklistMatrixVehicle=4432&type=1&model=Forester Wilderness w/Continuously Variable Transm)

Identified ADAS Systems

<u>System</u>	<u>Component</u>	<u>Location</u>
Adaptive Cruise Control	EyeSight Stereo Camera	Windshield
Backup Cameras	Rear View Camera	Trunk Lid
Blind Spot Monitoring Systems	Blind Spot Sensors	Rear Quarter Panels
Occupant Detection	Occupant Detection System	Passenger Seat
Parking Assist Systems	Front View Camera Assembly	Front Bumper
	Sonar Sensors	Rear Bumper
Seat Belt Inspection	Seat Belt	Interior
Steering Angle Sensor	Steering Angle Sensor	Column

The Fine Print:

The Fine Print (Legaleze)

The ADAS MAP™ report is for informational purposes only and should not be considered as a replacement for Original Equipment Manufacturers (OEM) diagnostic, repair or calibration recommendations and procedures. The ADAS MAP™ platform utilizes data from multiple sources such as VIN, ADAS and safety system build data. While this data is considered accurate, Auto Techcelerators, LLC. makes no guarantees about its accuracy or completeness because it is being generated and delivered by third-parties.



North Star Moon Twp
5854 University Blvd
Moon Twp, PA 15108

Collision Calibration Requirements:

- Even minor collisions may affect camera axis alignment, requiring recalibration.
- Subaru defines a collision as any damage beyond cosmetic body panel distortion.
- Calibrate even if no warning messages are displayed.

Calibration Steps:

- ADAS targets are required for system calibration and requires a dynamic drive to finalize the calibration.
- ClearActive Lane Keep System after a four-wheel alignment or suspension work.
- PerformVDC 0-point adjustment.

Additional Recommendations:

- UseOE glass for replacements.
- Ensure tire inflation pressure is correct, the vehicle is unloaded, and the fuel tank is full.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3123749&adasChecklistMatrixVehicle=1974&type=1&model=Forester Wilderness w/Continuously Variable Transm)

[adasInspection=3123749&adasChecklistMatrixVehicle=1974&type=1&model=Forester Wilderness w/Continuously Variable Transm](https://opusadas.z13.web.core.windows.net/links?adasInspection=3123749&adasChecklistMatrixVehicle=1974&type=1&model=Forester Wilderness w/Continuously Variable Transm)

Blind Spot Monitoring Systems

Blind Spot Sensors

Rear Quarter Panels

ADAS L3: Static Calibration - B

Calibrate Blind Spot Detection (BSD) when the following are removed, installed / replaced, or repairs in the immediate mounting area: quarter panel, rear body panel, sensor, sensor bracket. Subaru also states the BSD system should be calibrated if the rear bumper is damaged and makes mention of replacing the rear bumper cover if there is any damage within the sensor viewing area (inside or outside). Before calibration verify the inflation pressure of tires is correct, vehicle does not have load, and vehicle's fuel tank is fully filled. ADAS targets are required for system calibration.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3123749&adasChecklistMatrixVehicle=770&type=1&model=Forester Wilderness w/Continuously Variable Transm)

[adasInspection=3123749&adasChecklistMatrixVehicle=770&type=1&model=Forester Wilderness w/Continuously Variable Transm](https://opusadas.z13.web.core.windows.net/links?adasInspection=3123749&adasChecklistMatrixVehicle=770&type=1&model=Forester Wilderness w/Continuously Variable Transm)

Occupant Detection

Occupant Detection System

Passenger Seat

Seat Related Calibration

Subaru service information states that the Occupant Detection System must be calibrated and zeroed each time a seat component is removed, loosened, or replaced. The system should be inspected if the vehicle has been in a collision. The seat must be upright and empty, dry, and free from any aftermarket covering when performing the zeroing. The zero procedure may need to be repeated more than once in some instances.

OEM Reference:

[https://opusadas.z13.web.core.windows.net/links?](https://opusadas.z13.web.core.windows.net/links?adasInspection=3123749&adasChecklistMatrixVehicle=4369&type=1&model=Forester Wilderness w/Continuously Variable Transm)

[adasInspection=3123749&adasChecklistMatrixVehicle=4369&type=1&model=Forester Wilderness w/Continuously Variable Transm](https://opusadas.z13.web.core.windows.net/links?adasInspection=3123749&adasChecklistMatrixVehicle=4369&type=1&model=Forester Wilderness w/Continuously Variable Transm)

Parking Assist Systems

Sonar Sensors

Rear Bumper

ADAS L1: Initialization / Programming

Sonar Height Angle Inspection is to be completed when the rear bumper is replaced or sensors are removed.