

Final Rework Details





TotalQty

10,06,024

AcceptedQty

0

ConAcceptedQty

350

RejectedQty

745


ReworkQty

0.03%

% Rejection


0.07%

% Rework



Rejection Details

PartName	Reason	TotalQty	RejectedQty	% Rejection ▼		
☐ Crossmember Assy	FORMING OFFSET	24	24	100.00%		
		8	0	0.00%		
☐ ENGINE MTG FLITCH RH	IMPROPER FORMING	3	3	100.00%		
		138	0	0.00%		
☐ CROSS MEMBER	FORMING HOLE OFFSET	30	30	100.00%		
	FORMING OFFSET	6	6	100.00%		
		2,385	0	0.00%		
□ ENG MTG FLITCH RH	DIMENSION VARIATION	2	2	100.00%		





Final Rejection Details



Customize your Analysis by Top# 50

10,15,954

TotalQty

10,06,024

AcceptedQty

0

ConAcceptedQty

350

RejectedQty

745


ReworkQty

0.03%

% Rejection

0.07%

% Rework



Rework Details								
PartName	ReasonName	TotalQty ▼	ReworkQty	% Rework				
☐ FLITCH LH	HOLES DAMAGE	94	2	2.13				
	WRONG PART NO PUNCHING	94	2	2.13				
	OLD VERSION	88	88	100.00				
	MATERIAL DAMAGE	1	1	100.00				
☐ FLITCH RH	OLD VERSION	57	57	100.00				
	MATERIAL DAMAGE	34	34	100.00				
☐ INTERNAL FLITCH RH	OLD VERSION	4	4	100.00				
	MATERIAL DAMAGE	2	2	100.00				

ReworkQty Det	ails	
ENG MFG FLITC		136
FLITCH LH		91
FLITCH RH		91
INTERNAL FLIT		87
BATTERY BOX /		84
STIFFNER FLIT	40	
EXT FLITCH LH	37	
ENG MTG FLITC	30	
ENG MTG FLITC	26	
REAR SUSBENS	26	
FLITCH RH FRO	17	
INTERNAL FLIT	10	
ENG MFG FLITC	9	
EXTERNAL FLIT	7	
INTERNAL FLIT	6	
FLITCH RH FOR	5	
INTERNAL FLIT	5	
EXTERNAL FLIT	4	
EXTERNAL FLIT	4	
Flitch LH Extern	4	
FRAME FLITH R	4	
EXTERNAL FLIT	3	
FLITCH	3	
INTERNAL FLIT	3	
ENGINE MTG FL	2	
FLITCH LH FRONT	2	



Rejection & Rework PPM & Sigma Levels



PartNo

PartName

1st Time Quality Details

PartName	1st Time Yield	PPM Value	Sigma Level
CHANNEL	100.00%	0.00	+inf
LD BRACKET BOTTOM BRACKET TYP 01/C FOR M12	100.00%	0.00	+inf
TEMPLATE -ITEM-1	100.00%	0.00	+inf
(OIP) WHEEL DISC A	100.00%	0.00	+inf
(OIP) WHEEL DISC B	100.00%	0.00	+inf
1" WORM CLAMP	100.00%	0.00	+inf
15KVA ENGINE,20KVA CGL ALTERNATOR 3PH KERELA SPEC DG GET	100.00%	0.00	+inf
16T FUPD	100.00%	0.00	+inf
1MM PACKING PLATE REAR MTG	100.00%	0.00	+inf
Total	99.89%	1,077.80	3.07

Overall Quality Details

PartName	Overall Yield	PPM Value	Sigma Level
CHANNEL	100.00%	0.00	+inf
LD BRACKET BOTTOM BRACKET TYP 01/C FOR M12	100.00%	0.00	+inf
TEMPLATE -ITEM-1	100.00%	0.00	+inf
(OIP) WHEEL DISC A	100.00%	0.00	+inf
(OIP) WHEEL DISC B	100.00%	0.00	+inf
1" WORM CLAMP	100.00%	0.00	+inf
15KVA ENGINE,20KVA CGL ALTERNATOR 3PH KERELA SPEC DG GET	100.00%	0.00	+inf
16T FLIPD	100.00%	0.00	+inf
Total	99.97%	344.50	3.39

Quality Check

PartName	Quality Check
BATTERY BOX / TOP FRAME 9T	1st Time Failed
ENG MFG FLITCH LH	1st Time Failed
ENG MFG FLITCH RH	1st Time Failed
ENG MTG FLITCH LH	1st Time Failed
ENG MTG FLITCH RH	1st Time Failed
ENGINE MTG FLITCH LH	1st Time Failed
ENGINE MTG FLITCH RH	1st Time Failed
EXT FLITCH LH	1st Time Failed
EXTERNAL FLITCH - LH	1st Time Failed
EXTERNAL FLITCH LH	1st Time Failed
EXTERNAL FLITCH LH AT REAR SP	1st Time Failed
EXTERNAL FLITCH LH FRONT	1st Time Failed
EXTERNAL FLITCH REAR LH	1st Time Failed
EXTERNAL FLITCH REAR RH	1st Time Failed
EXTERNAL FLITCH RH	1st Time Failed
EXTERNAL FLITCH RH ATREAR SP	1st Time Failed
EXTERNAL FLITCH RH FRONT	1st Time Failed
FLITCH	1st Time Failed
FLITCH LH	1st Time Failed
Flitch LH External 1616 IL1 18	1st Time Failed
FLITCH LH FRONT	1st Time Failed
FLITCH RH	1st Time Failed
FLITCH RH FOR 135KW LT WITH	1st Time Failed
EI ITOU DU EDONIT	1st Time Foiled



Cost of Quality

Clear all slicers

ı	Financial Year	~	Month Name	~	PartNo	× .	PartName	Re	ejection Reason	Rework Reason	· ·
ı	All	~	All	~	All	~	All 🗸	All	II ~	All	~

PartNo	PartName	TotalQty ▼	RejectedQty	Wt Avg Rate	Cost of Quality	%Cost
FG-SE0022-AA	U-PANEL RAIL GENERIC MODULE	74,715	0	180.00	0.00	0.00%
FG-SE0006-AA	JOURNAL HALF UPPER	36,126	0	99.41	0.00	0.00%
FG-MD0002-AA	DAT MOUNTING BRACKET	33,733	0	58 . 50	0.00	0.00%
FG-MD0001-AA	ARM BRACKET ASSY. LH	32,046	0	77.50	0.00	0.00%
FG-SE0007-AA	LOWER JOURNAL WELD ASSY	31,462	0	365.34	0.00	0.00%
FG-SE0011-AA	COUPLER END HALF CLAMP	27,763	0	251.19	0.00	0.00%
FG-BI0001-AA	TUBE FLANGE BRACKET ASSY.	27,424	0	268.58	0.00	0.00%
FG-DM0012-AA	REINFORCEMENT PLATE / SIDE STOPPER/6X4C	23,966	0	220.87	0.00	0.00%
FG-BI0002-AA	TUBE FLANGE BRACKET ASSY.	23,061	0	272.05	0.00	0.00%
FG-BM0001-AA	S/A OF BUMPER	21,538	0	1,053.71	0.00	0.00%
FG-BI0003-AA	TUBE FLANGE BRACKET ASSY.	20,511	0	278.23	0.00	0.00%
FG-B I 0004-AA	TUBE FLANGE BRACKET ASSY.	20,140	0	278.86	0.00	0.00%
FG-SE0005-AA	SIDECLAMP I BEAM DAMPER MOUNT	19,455	0	124.57	0.00	0.00%
FG-BM0003-AA	FRONT BUMPER - CARGO	18,832	0	755.66	0.00	0.00%
FG-IC0007-AA	WINDOW BAR TO DRG NO.ICF/STD 10 012 ITEM.19 ALT H.	18,297	0	20.94	0.00	0.00%
FG-MD0004-AA	SIDE FRAME ASSY. LH-HDT	17,192	9	280.40	2,523.60	1.90%
FG-MD0003-AA	SIDE FRAME ASSY. RH-HDT	16,313	12	407.00	4,884.00	3.68%
FG-AM0003-AA	SA OF FRONT STAY	15,614	0	406.54	0.00	0.00%
FG-SE0009-AA	THRUST STOP CLAMP	13,643	0	22.56	0.00	0.00%
FG-DM0089-AA	CORRUGATED RAIL DOUBLE HAT SECTION	10,695	0	293.50	0.00	0.00%
FG-SE0023-AA	Damper lever.	10,436	0	136.54	0.00	0.00%
Total		10,15,954	350	379.39	1,32,786.53	100.00%