

DDA PARK, ROHINI — SAFETY & SECURITY

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: DDA Park, Rohini, Rohini (DDA)

Survey date: 20 May 2026, 12:12-12:43 IST (single-date baseline)

Category: Safety & Security

CATEGORY SCORE				
Indicator	Mean	Min	Max	Rating
Safety	95.6%	90.8%	96%	Good

DETECTOR FINDINGS				
Detector class	Records	Mean cond. %	Worst %	Condition
Vehicle in Premises	0	—	—	Not observed in these clips
Low-Visibility Zone	89	68.1	66	Fair
Construction Activity	0	—	—	Not observed in these clips
Excavation / Disturbed Ground	0	—	—	Not observed in these clips

ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
219	Lawns, gazebo & hedge beds	Low-Visibility Zone	Low	67.4	Low-visibility zone - schedule a ground or low-altitude patrol.
220	Lawns, gazebo & hedge beds	Low-Visibility Zone	Low	67.5	Low-visibility zone - schedule a ground or low-altitude patrol.
221	Lawns, gazebo & hedge beds	Low-Visibility Zone	Low	68.1	Low-visibility zone - schedule a ground or low-altitude patrol.
222	Lawns, gazebo & hedge beds	Low-Visibility Zone	Low	68.6	Low-visibility zone - schedule a ground or low-altitude patrol.
223	Lawns, gazebo & hedge beds	Low-Visibility Zone	Low	68.8	Low-visibility zone - schedule a ground or low-altitude patrol.
224	Lawns, gazebo & hedge beds	Low-Visibility Zone	Low	69	Low-visibility zone - schedule a ground or low-altitude patrol.

RECOMMENDED ACTIONS				
#	Priority	Finding	Recommended action	Owner
2	Critical	The site record notes exposed electric wires laid in the open, utility damage and an unsafe bridge. None of these is detectable from RGB drone imagery at survey altitude, so the report cannot measure them - but an exposed live conductor in a public park is a life-safety issue.	Commission an immediate ground safety inspection covering electrical services, the bridge structure and any open utility. Do not wait on drone evidence for this - the technology cannot see it.	Engineering / Safety

