

SMRITI VAN MAYUR VIHAR — ASSET INVENTORY

Category export · AI Drone Survey · DDA / DTU parameter framework

Site: Smriti Van Mayur Vihar, Mayur Vihar (DDA)

Survey date: 19 May 2026, 16:54-17:35 IST (single-date baseline)

Category: Asset Inventory

DETECTOR FINDINGS					
Detector class		Records	Mean cond. %	Worst %	Condition
Tree Stem		3384	91.5	43.7	Good
Bench		178	75.4	68.1	Good
Play Equipment		1014	83.9	56.1	Good
Open Gym Equipment		195	81.9	64.9	Good
Walking Track		335	52.9	34.4	Poor
ANOMALIES (worst first)					
Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
26	Children's play area	Walking Track	High	37.1	Resurface and reinstate the track after the works.
39	Children's play area	Walking Track	High	40.1	Resurface and reinstate the track after the works.
41	Children's play area	Walking Track	High	40.6	Resurface and reinstate the track after the works.
60	Children's play area	Walking Track	High	44.4	Resurface and reinstate the track after the works.
97	Children's play area	Walking Track	Medium	48.5	Resurface and reinstate the track after the works.
109	Waterlogged ground	Walking Track	Medium	49.3	Resurface and reinstate the track after the works.
126	Children's play area	Walking Track	Medium	50.4	Resurface and reinstate the track after the works.
130	Lawns & tree belt	Walking Track	Medium	50.5	Resurface and reinstate the track after the works.
131	Children's play area	Walking Track	Medium	50.6	Resurface and reinstate the track after the works.
148	Children's play area	Walking Track	Medium	52.4	Resurface and reinstate the track after the works.
157	Children's play area	Walking Track	Medium	53.7	Resurface and reinstate the track after the works.
171	Waterlogged ground	Walking Track	Medium	54.5	Resurface and reinstate the track after the works.
174	Children's play area	Walking Track	Medium	54.7	Resurface and reinstate the track after the works.
189	Children's play area	Tree Stem	Medium	55.4	Field verification required.
198	Children's play area	Walking Track	Medium	57.2	Resurface and reinstate the track after the works.
204	Waterlogged ground	Walking Track	Medium	57.7	Resurface and reinstate the track after the works.
213	Flooded planting bed	Tree Stem	Medium	59.4	Field verification required.

Priority	Zone	Anomaly	Severity	Cond. %	Suggested action
216	Children's play area	Tree Stem	Medium	59.6	Field verification required.

RECOMMENDED ACTIONS

#	Priority	Finding	Recommended action	Owner
4	High	A piece of children's play equipment appears collapsed on the ground in the play-area clip, and the sand surface beneath the equipment is bare and hard-packed.	Inspect and make safe immediately - remove or reinstate the fallen unit, and replace the impact-absorbing surface under all play equipment.	Engineering / Works

Generated from Smriti_Van_AI_Detection_Report.xlsx · DDA AI Park Monitor. Figures are the park-wide mean across 4 analysed clips, recomputed directly from the detection log rather than the workbook's own summary formulas.