

Alternate phases
SM 0
SM 1
SM 2
SM 3
S
S
S
intra
intra
intra
time
One fused kernel
SM 0
SM 1
SM 2
SM 3
h1 c1
h1 c2
h1 c3
h1 c4
h2 c1
h2 c2
h2 c3
h2 c4
intra-chunk work
state hand-off
idle SM
h = head · c = chunk