

Zeroing criteria for the coefficients														
	r	r_dot	q	q_dot	r^2	r_dot^2	q^2	q_dot^2	r^2 r_dot	r^2 q	r^2 q_dot	r_dot^2 q	r_dot^2 q_dot	q^2 q_dot
r	3.758	0.001	3.765	2.735	12.745	15.070	12.752	15.074	612.043	261.633	932.931	330.149	60.157	319.748
r_dot	0.001	0.003	0.001	2.988	6.868	10.358	16.111	262.295	6.476	8.547	8.724	6.629	1.334	8.904
q	3.783	3.151	3.752	0.000	17.560	21.843	17.517	21.025	5.465	3.836	32.879	3.980	7.997	8.219
q_dot	0.058	0.547	0.009	0.006	7.176	9.431	9.743	9.721	6.009	19.849	3.657	3.649	3.645	0.005