Accelerator keys

General

Alt+Backspace Undo

Alt+F4 Exit Program
Alt+Z Statistics
Ctrl+Num+ Zoom-In
Ctrl+Num- Zoom-Out
Ctrl+0 Main Tool Bar

Ctrl+1-9 Component Palette 1-9

Ctrl+A Select All
Ctrl+C Copy

Ctrl+Delete Clear Cut Wire

Ctrl+F Find

Ctrl+F4 Close Open Window
Ctrl+F6 Next Window

Ctrl+Insert Copy New File Ctrl+N Ctrl+O Open File Ctrl+P Print Save File Ctrl+S Ctrl+Alt+R Revert File Ctrl+V Paste Shift+Insert Paste Ctrl+X Cut Ctrl+Y Redo Ctrl+Z Undo

Ctrl+Shift+BBill of MaterialsCtrl+Shift+FFind ComponentCtrl+Shift+GGlobal SettingsCtrl+Shift+IIBIS TranslatorCtrl+Shift+PPreferences

Ctrl+Shift+W Print Active Window

Del Clear F1 Help

Alt+F10 Default Properties
F10 Properties
Shift+F4 Tile Vertical

Shift+F5 Cascade

Schematic / Text Area

Alt+9

Delete Delete selected objects Alt+1**Transient Analysis** Alt+2AC Analysis Alt+3 DC Analysis Dynamic DC Alt+4Dynamic AC Alt+5 Sensitivity Alt+6 **Transfer Function** Alt+7 Alt+8 Harmonic Distortion

Ctrl+B Move text

Ctrl+Delete Delete wires at box
Ctrl+End Lower Right Schematic

Intermodulation Distortion

Ctrl+F Find

Ctrl+Alt+1 Probe Transient
Ctrl+Alt+2 Probe AC
Ctrl+Alt+3 Probe DC

Ctrl+D Component Mode Ctrl+E Select Mode

Ctrl+G Toggle Drawing/Text

Ctrl+H Help Mode

Ctrl+Home Upper Left Schematic

Ctrl+I Info Mode
Ctrl+M Make Macro
Ctrl+R Rotate Box
Ctrl+W Wire Mode

Ctrl+Shift+R Toggle Rubberbanding

Ctrl+LeftPan LeftCtrl+RightPan RightCtrl+UpPan UpCtrl+DownPan Down

PgUp Pan Up One Page
PgDn Pan Down One Page
Ctrl+PgUp Pan Left One Page
Ctrl+PgDn Pan Right One Page
Ctrl+] Match Parenthesis
F3 Repeat Last Find

Text Area / Text File

Alt+F1 SPICE Help
Ctrl+D Delete Line
Ctrl+L Set to Lowercase
Ctrl+U Set to Uppercase

Schematic / Analysis

Ctrl+T Text Mode

Spacebar Toggle between Select mode and current mode

Analysis

Ctrl+N Normalize

Ctrl+F9 Delete All Plots - Probe

Ctrl+F11 Optimize

Restore Scale Limits Ctrl+Home Ctrl+I Intercept Tracker Tag Left Cursor Ctrl+L Mouse Tracker Ctrl+M Ctrl+N Normalize at Cursor Tag Right Cursor Ctrl+R Cursor Tracker Ctrl+Shift+C Ctrl+Shift+H Tag Horizontal Tag Vertical Ctrl+Shift+V Ctrl+Shift+X Go to X Go to Y Ctrl+Shift+Y

F2 Run Analysis
F3 Exit Analysis
F4 Analysis Window
F5 Numeric Output

F6 Auto Scale
F7 Scale Mode
F8 Cursor Mode
F9 Limits
F11 Stepping

F12 State Variables Editor Down Arrow Left Cursor Down a Branch

Left Arrow
Right Arrow
Left Cursor to Left
Left Cursor to Right
Up Arrow
Left Cursor Up a Branch
Shift+Dn Arr
Right Cursor Down a Branch

Shift+Lft Arr Right Cursor to Left
Shift+Rt Arr Right Cursor to Right
Shift+Up Ar Right Cursor Up a Branch

Ctrl+Down Arr
Ctrl+Left Arr
Ctrl+Right Arr
Ctrl+Up Arrow
Ctrl+W
Pan Plot Down
Pan Plot Left
Pan Plot Right
Pan Plot Up
Watch Mode

Alt+Home Place Cursor on Top Branch

Alt+End Place Cursor on Bottom Branch

3D Plot

Q Clockwise X

A Counterclockwise X W Clockwise Y

S Counterclockwise Y

E Clockwise Z

D Counterclockwise Z
C Toggle Contour / 3D
X Perpendicular to x=0
Y Perpendicular to y=0
Z Perpendicular to z=0