# **Project #3 Drawing and Tolerances**

#### ME 366 Computer Aided Engineering & Manufacturing

Will Buziak December 1<sup>st</sup>, 2021

#### Overview

The task for this project was to use calipers to measure a given object, redesign in solidworks and use tolerancing to produce a fit that is appropriate for this assembly. In this project we learned the importance of accurate measurement and it's impact on tolerancing and fits. My part's measurements did not allow a loose running fit on the minor diameter due to the part being outside of the tolerance.






Figure 1.


#### **Part Measurements**




**Table 1.** Dimensions of Major and Minor Diameters


#### **Part Files**






## **Assembly File**






#### **Fit Selection and Tolerances**

Loose running fit does not work on minor diameter, could be result of caliper error






	Minor Diameter			Major Diameter		
	Loose running			sliding		
	H11/C11			H7/G6		
	Base	Upper Limit	Lower Limit	Base	Upper Limit	Lower Limit
Pin	.5950	.5913	.587	.8880	.8876	.8869
Housing	.5950	.6042	.5950	.8880	.8892	.8880
Clearance	.008			.004		
Allowance	.008			.0023		

 Table 2. Calculated Tolerances for Major and Minor Diameters

### **Drawings**



#### **Conclusion**

My group had issues finding a tolerance for the minor diameter. I experienced the hole being outside of the allowance for even the loosest fit, however the major diameter was much closer to the base allowing a sliding fit. My hypothesis is that there was either human or caliper error which resulted in a miscalculated measurement. I believe that if there were a more unbiased measurement (mainly, separate measurements that are then checked and agreed upon instead of one measurement that is agreed upon) would reduce this error and perhaps allow at least a loose running fit.