


ITEM NO.	PART NUMBER	QTY.
1	Z Axis Stepper Mount_0.01	2
2	8mm Lead Screw 2 Start 300mm	2
3	nema17_0.01	2
4	Lead Screw Flexible Coupler_0.01	2
5	8mm precision rod 400mm_0.01	4
6	M3 washer_0.01	8
7	Z Axis 8mm Shaft Mount_0.01	8
8	M3 Nut	8
9	M3 x 12mm Socket Head Screw	8
10	M3 x 10mm Socket Head Screw	8
11	ISO 7380 - M5 x 10 - 10N	24







**GENERAL NOTES** 

REVISION

DATE

CHANGE NOTES

01/03/2017

210

\_( 105 )

105

DIMENSIONS IN MILLIMETRES 0-250mm

PARTS TO BE CLEAN AND FREE FROM OIL AND GREASE

THE USER OF THIS DRAWING IS RESPONSIBLE FOR ENSURING THEY HAVE THE LATEST ISSUE

REMOVE ALL SHARP EDGES AND BURRS

DO NOT SCALE. WORK TO DIMENSIONS ONLY

DRAWN BY

**ENGINEER** 

A Meadows

**AMEADOWS** 

TOLERANCES 250-1000mm TOLERANCE HEIRARCHY IN DESCENDING ORDER ±0.1mm ±0.2mm ±0.5mm MACHINING + 0.3 mm <sup>+0.5</sup> mm HOLE SIZE +<sup>0.5</sup> mm HOLE POSITION ±0.3mm ±0.5mm ±0.5mm FORM/PROFILE ±0.5mm ASSEMBLIES/FABRICATIONS ±0.5mm ±1.0mm ±0.3° ±0.1°

**MATERIAL** SEE COMPONENT PARTS SIZE SEE COMPONENT PARTS MATERIAL SEE COMPONENT PARTS **SPEC FINISH** None 1:5 DRAWING SCALE

А3

TITLE: Z Axis Assembly\_0.01

STATUS: Released

ESTIMATED MASS 0.38Kg

DRAWING SIZE

SHEET 1 OF 1

- NUTS SHOULD BE PRE ASSEMBLED TO FRAME - TO BE ASSEMBLED DIRECTLY ONTO COMPLETED FRAME - USING THE FRAME AS A REFERENCE, ENSURE Z AXIS SHAFT ARE PARALLEL AND VERTICAL.