





## ErgoMax StripBoard | placement (component side)

Print at 100% / actual size, disable "fit to page", then verify the ruler. Lay this on the component side and push leads through the marked holes.



## ErgoMax StripBoard | track cuts (copper side, mirrored)

Mirrored for the underside. Cut each X. Verify the ruler.



## ErgoMax StripBoard | bill of materials

| Qty | Component         | Value | References                                                    |
|-----|-------------------|-------|---------------------------------------------------------------|
| 10  | Connector (1-pin) | -     | 5V, ~3, ~5, ~6, ~11, A0, A1, A2, A3, GND                      |
| 8   | Connector (2-pin) | -     | FSR1, FSR2, FSR3 (diff), FSR4, Motor1, Motor2, Motor3, Motor4 |
| 4   | Diode             | -     | D1, D2, D3, D4                                                |
| 4   | NPN Transistor    | -     | Q1, Q2, Q3, Q4                                                |
| 3   | Resistor          | 22000 | R1, R2, R4                                                    |
| 1   | Resistor          | 47000 | R3                                                            |
| 4   | Resistor          | IDK   | R5, R6, R7, R8                                                |