Introduction

According to [Guide] Alternative to the minStolenSize patch with 32mb DVMT-prealloc, "[a] common problem with Broadwell/Skylake/KabyLake is relatively small DVMT-prealloc setting by PC OEMs. The Apple framebuffer kexts generally assume 64mb or larger, and most PC OEMs use only 32mb." So we patched the framebuffer in EFI to fit within the 32mb DVMT-prealloc.

However, I found that 32mb DVMT seems doesn't support 4K display even with -cdfon boot argument in the XiaoMi-Pro case. Set DVMT to 64mb and remove some framebuffer patches could let our hacks natively support 4K.

ATTENTION: HDMI ports use HDMI 1.4 protocol, which means only support 4K 30Hz HDMI.

How to Install

- TM1701
- TM1707
- TM1905

TM1701

Cyb and FallenChromium created script to set DVMT. Please download DVMT_and_0xE2_fix and read README to set DVMT to 64mb.

After running those scripts, you need to remove some framebuffer patches:

- For both Clover and OC users:
- Open /EFI/CLOVER (or OC)/config.plist, delete the following code:

```
<key>framebuffer-fbmem</key>
<data>AACQAA==</data>
<key>framebuffer-stolenmem</key>
<data>AAAwAQ==</data>
```

ullet Then edit the framebuffer-flags to enable FBEnableDynamicCDCLK and restart

```
<key>framebuffer-flags</key>
- <data>CwfDAA==</data>
+ <data>CwfjAA==</data>
```

TM1707

The following table is about some advanced BIOS configurations, thanks to goodyttoor.

Item	Address	Options
DVMT Pre-Allocated	$0 \mathrm{xDF}$	0x1: 32M (default), 0x2: 64M (recommend)
DVMT Total Gfx Mem	0xE 0	0x1: 128M, 0x2: 256M (default), 0x3: MAX (recommend)
CFG Lock	0x3C	0x0: Disabled (recommend), 0x1: Enabled (default)
BIOS Lock	0x17	0x0: Disabled (recommend), 0x1: Enabled (default)

Then refer to TM1701 to edit config.plist.

TM1905The following table is about some advanced BIOS configurations, thanks to htmambo.

Item	Address	Configuration	Options	Default	Recommend
RTC	0x54A	SETUP	0x0:ACPI	0x0	0x1
			Time and		
			Alarm Device;		
			0x1:Legacy		
			RTC		
DVMT	0x107	SaSETUP	0x0:0M,	0x1	0x2
			0x1:32M,		
			0x2:64M		
DVMT Total Gfx Mem	0x108	SaSETUP	0x1:128M,	0x3	0x3
			0x2:256M,		
			0x3:Max		
CFG LOCK	0x3E	CpuSetup	0x0:Disabled,	0x1	0x0
			0x1:Enabled		
MSR LOCK	0x2B	SETUP	0x0:Disabled,	0x0	0x0
			0x1:Enabled		
BIOS Lock	0x17	SETUP	0x0:Disabled,	0x1	0x0
			0x1:Enabled		

After modifying these configurations, you need to delete framebuffer-stolenmem in config.plist: - Open /EFI/CLOVER (or OC)/config.plist, delete the following code:

<key>framebuffer-stolenmem</key> <data>AADgAQ==</data>

Credits

- Rehabman
 - [Guide] Alternative to the minStolenSize patch with 32mb DVMT-prealloc
- Cyb, FallenChromium, and goodyttoor for efforts on 8th Gen model
 htmambo for efforts on 10th Gen model