

Address Settings
WatchDog
27550
All Zero Reset
Create From Sensor1
Save CSV File
Load CSV File
Load PLC
Enable Sensor PressAddress ValveAddress BaseAddress PPRatioAddress SPAlarmAddress QuleeAlarmAddress ModeAddress RcpUnitAddress TotalPressAddress ChamberName
V AddressSensor1 27400 27408 27551 27591 27595 27615 27616 0 0 S3
V AddressSensor2 27401 27409 27621 27661 27665 27685 27686 0 0 S4
V AddressSensor3 27402 27410 27691 27731 27735 27755 27756 0 0 S5
V AddressSensor4 27403 27411 27761 27801 27805 27825 27826 0 0 S6
V AddressSensor5 27404 27412 27831 27871 27875 27895 27896 0 0 T0
AddressSensor6 0 0 0 0 0 0 0 0 0
AddressSensor7 0 0 0 0 0 0 0 0 0
AddressSensor8 0 0 0 0 0 0 0 0 0