

From: Joe Barrett jbarrett@theflooringcenterorlando.com
Subject: Re: Claim Report
Date: September 2, 2025 at 4:45 PM
To: Austin Tyler austintyler123@hotmail.com

JB

Hi Austin:
Regarding the moisture readings, operations says:

We do not initiate a report unless we have concerns. If he would like us to go out again and get accurate readings that is manageable.

However at time of installation no high readings were met

Joe Barrett, Sales Manager

The Flooring Center, Dr. Phillips Branch
7600 Dr. Phillips Blvd, Suite 148
Orlando, FL 32819--
407.248.7788

From: Austin Tyler <austintyler123@hotmail.com>
Date: Saturday, August 30, 2025 at 12:40 PM
To: Joe Barrett <jbarrett@theflooringcenterorlando.com>
Subject: Re: Claim Report

Hi Joe,

The installation checklist you attached says "All Relative Humidity & Moisture levels (Plywood, Slab and Hardwood) will be tested, documented and a copy given to the customer for their records." Are you able to provide these?

Thanks,

Austin Tyler

On Aug 30, 2025, at 5:21 PM, Joe Barrett
<jbarrett@theflooringcenterorlando.com> wrote:

Hi Austin:

Forwarding this information from our operations manager. Some perspective and assurance that we do things correctly, and that we will ensure anything that is not correct will be addressed.

Best wishes,

Joe Barrett, Sales Manager

The Flooring Center, Dr. Phillips Branch
7600 Dr. Phillips Blvd, Suite 148
Orlando, FL 32819--
407.248.7788

From: Eric Rusnak <erusnak@theflooringcenterorlando.com>
Date: Friday, August 29, 2025 at 1:55 PM
To: Joe Barrett <jbarrett@theflooringcenterorlando.com>
Subject: Claim Report

Hi Joe

Per Manufacturing. We will need pictures of the hardwood and the sample.

The rep will file a claim accordingly however, hardwood variation in character, color and texture vs the sample, is not a defect per our guidelines, per the sample, per the warranty provided.

In regards to a few of the comments or concerns.

Our warehouse stays from 75-82 all year except during extreme cold temperatures. We absolutely check the subfloor, relative humidity and hardwood moisture content prior to installation. A second floor is highly unlikely to have high levels of moisture as it is plywood.

The repair fixed the issue, if we stopped originally...that would've needed a framer.

I am sorry this should have been brought up to at least give the customer an opportunity to have a conversation

Thanks, talk soon

Eric Rusnak
The Flooring Center
President
407-660-8400
erusnak@theflooringcenterorlando.com

<doc04388420250829133732.pdf><doc04388520250829134650.pdf>

Caution: This email originated from outside of your organization. Do Not click links or open attachments unless you recognize the sender and know the

content is safe. When in doubt, Delete the Message.