

LeakTrace AI Investigation Report

Case Number: LT-20260605113352

Property Address: 123 main st hahira, GA 31632

Roof Type: 3-Tab Asphalt Shingle

Most Probable Leak Source

Roof Penetration / Vent Flashing Failure

AI Diagnosis

Failed seal, cracked boot, loose flashing, exposed fasteners, or separation around a roof penetration.

Repair Recommendation

Replace or properly reflash the failed penetration detail, reseal fasteners, and inspect surrounding decking.

Confirmation Steps

Inspect penetrations above the leak area. Look for cracked rubber, lifted flashing, failed sealant, backed-out fasteners, or separation. Perform a controlled hose test around one penetration at a time.

Estimated Repair Range

\$350–\$850

Weather Correlation

No weather data

Uploaded Evidence Count: 0 photos

Generated by LeakTrace AI