WO#: 2018 01379

91SA

1710

Cirrus

SR-20

5550.0

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Western Michigan University **College of Aviation**

Work Order

A/C Total Time: 5550.0

08/30/18

08/31/18

RT Eng. T.T.: RT Prop. T.T.

Date Started:

Date Completed:

LT Eng T.T.: 1557.5 LT Prop T.T.: 3704.5

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

Description of Work to be Performed RH white position light inop Maintenance/Repairs Performed 1) RH white position light inop Airframe: Replaced RH white position light bulb. Ops check good. Labor 001:00 Kevin Luther 1.0 1:00 **Parts Used** Description Serial# Sub Total Qty Part# Cost 34-0428070-64 White Position Light (A508-28) 21.52 21.52 **Technician Release Work Order Totals** 75.00 Buy Back ☐ Test FLT ☐ Tech Signature: Labor Tech#: 21.52 Parts **Maintenance Release** TOTAL: 96.52 The aircraft, airframe, aircraft engine, propeller or appliance identified above, was inspected and Preliminary / Hidden repaired in accordance with current Regulations of the Federal Aviation Administration and is **Inspection Release** approved for return to service. Pertinent details of the repair/inspection are on file at the Repair Station under this Work Order. Date: Signed: Inspector: WMU FAA CertificatedRepair Station JX8R258Q . 237 N Helmer Road, Battle Creek, MI 49037