WO#: 2013 01038

91SA

1710

Cirrus

SR-20

3392.4

Reg#:

MFG:

Model:

A/C Tach Time:

AC S/N:

Work Order

Western Michigan University College of Aviation

FAA CertificatedRepair Station JX8R258Q 237 N Helmer Road, Battle Creek, MI 49037

09/04/13 Date Started: Date Completed: 09/05/13

A/C Total Time: 3392.4 RT Eng. T.T.: RT Prop. T.T. LT Eng T.T.: 1398.2 LT Prop T.T.: 3395.2

Description of Work to be Performed							
1)	Left aft nav light burnt out						

1) Left aft nav light burnt out								
Maintenance/Repairs Performed								
Airframe:	aft nav light burnt out							
Removed and replaced LH rear postion bulb. Ops check good.								
Labor								
Justine Fo	oster 1.0 001:00				1:00			
Parts Used								
Qty	Part#	Description	Serial#	Cost	Sub Total			
1 3	4-0428070-64	White Position Light (A508-28)		22.80	0 22.80			
	Т		Work Order Totals					
Buy Bac	k□ Test FLT□Tecl	Labor Parts	75.00 22.80					
	M		TOTAL:	97.80				
repaired in approved t	ft, airframe, aircraft engine, part accordance with current Refor return to service. Pertinel der this Work Order.	Preliminary / Hidden Inspection Release Date:						
	e: \$ FAA CertificatedRepair Station J	Signed: X8R258Q . 237 N Helmer Road, Battle Cre	ek, MI 49037	Inspector:				