





↓ Arduino gap should increase by 1-2 mm

Revise this structure for more strength

holes not aligned well with battery holder



adding resting plate will remove rocking motion

DC motor is locked in but rocks back and forth

- encoder does not lie completely flat, the soldering increases width by 1-2 mm.
- slot design and battery holder are perfect friction fits.
- encoder wheel is loose on the motor shaft.