STUDENT PROJECTS LABORATORY - 930 KINNEAR RD

STANDARD OPERATING PROCEDURE (SOP) | ASSET: CNC-03 | TAG: HURCO-CNC-01

CNC-03: Hurco CNC Turning Center / Lathe

Facility Zone: Zone 2: CNC Machining (CNC) | Supervisor: Max Wright (Sr. Instructional Lab Supervisor)

CRITICAL ENTANGLEMENT WARNING: STRICTLY NO GLOVES WHILE SPINDLE / BLADE IS ROTATING

1. REQUIRED PERSONAL PROTECTIVE EQUIPMENT (PPE)

1. ANSI Z87.1 Safety Glasses
2. Closed-Toe Shoes
3. No Loose Clothing or Jewelry
4. NO GLOVES Near Rotating Chuck

2. PRIMARY OPERATIONAL HAZARDS

1. High-RPM hydraulic chuck part ejection if jaw stroke or clamping pressure is incorrect
2. Turret index collision with tailstock or chuck jaws

3. BEFORE OPERATION CHECKLIST

1. Verify hydraulic chuck clamping pressure, jaw stroke limits, and turret tool clearances.
2. Check Z-zero and X-offset values before closing door.

4. DURING OPERATION SAFETY RULES

1. First-run prove-out at 5% rapid override with hand on E-Stop and enclosure door closed.
2. Listen for abnormal chatter or load meter spikes.

5. AFTER USE & SHOWROOM CLEANUP

1. Clear swarf with brush/washdown with machine completely stopped.
2. Home turret and power down via Utility Screen before turning off main breaker.

EMERGENCY SHUTDOWN & INCIDENT PROTOCOL:

Depress red E-Stop button on Hurco control console; wait for chuck and turret to stop completely.