STUDENT PROJECTS LABORATORY - 930 KINNEAR RD

STANDARD OPERATING PROCEDURE (SOP) | ASSET: SAW-04 | TAG: MITER-10-01

SAW-04: 10" Bevel Compound Miter Saw

Facility Zone: Zone 4: Cutting, Saws & Drilling (SAW) | Supervisor: Max Wright (Sr. Instructional Lab Supervisor)

CRITICAL ENTANGLEMENT WARNING: STRICTLY NO GLOVES WHILE SPINDLE / BLADE IS ROTATING

1. REQUIRED PERSONAL PROTECTIVE EQUIPMENT (PPE)

1. ANSI Z87.1 Safety Glasses
2. Hearing Protection
3. NO GLOVES Near Rotating Blade
4. Hair & Loose Sleeves Secured

2. PRIMARY OPERATIONAL HAZARDS

1. Blade contact and workpiece kickback if stock is not held firmly against fence
2. Coast-down laceration if hands reach into kerf before blade stops

3. BEFORE OPERATION CHECKLIST

1. Verify lower retractable blade guard operates smoothly.
2. Lock miter and bevel angle adjustments tightly before cutting.

4. DURING OPERATION SAFETY RULES

1. Keep hands at least 6 inches away from blade path; clamp small workpieces.
2. Allow blade to reach full speed before feeding into stock.

5. AFTER USE & SHOWROOM CLEANUP

1. Release trigger and wait for blade to come to a complete standstill before raising head.
2. Vacuum sawdust and offcuts from table.

EMERGENCY SHUTDOWN & INCIDENT PROTOCOL:

Release handle trigger immediately and keep saw head down until blade stops.