STUDENT PROJECTS LABORATORY - LOCKOUT / TAGOUT [LOTO] PROCEDURE

ENERGY ISOLATION SPECIFICATION | ASSET: SAW-01 | TAG: VSAW-01

Vertical Metal Cutting Bandsaw

Authorized LOTO Personnel: Sr. Instructional Lab Supervisor (Max Wright) & Student Research Assistants (SRAs)

Notification Channel: Max Wright - Teams / Text Message | Zone: Zone 4: Cutting, Saws & Drilling (SAW)

STEP 1 - NORMAL MACHINE SHUTDOWN PROCEDURE

Press red power switch OFF (Left side).

STEP 2 - HAZARDOUS ENERGY SOURCES, MAGNITUDES & ISOLATION POINTS

Source #1: Electrical (240V AC)

Isolation Location: 240V electrical plug & outlet behind saw.

Lockout Procedure: Unplug power cable from outlet and install Rotating Electrical Plug Lockout (from shop fence).

STEP 3 - STORED / RESIDUAL ENERGY DISSIPATION

Wait for bandsaw wheels and blade to coast to a complete stop; release blade tension before changing blade.

STEP 4 - ZERO-ENERGY VERIFICATION ('TRY' STEP)

Turn power switch ON and verify blade does not move.