STUDENT PROJECTS LABORATORY - LOCKOUT / TAGOUT [LOTO] PROCEDURE

ENERGY ISOLATION SPECIFICATION | ASSET: SAW-03 | TAG: CHOP-01

Abrasive Chop Saw

Authorized LOTO Personnel: Sr. Instructional Lab Supervisor (Max Wright) & Student Research Assistants (SRAs)

Notification Channel: Max Wright - Teams / Text Message | Zone: Zone 4: Cutting, Saws & Drilling (SAW)

STEP 1 - NORMAL MACHINE SHUTDOWN PROCEDURE

Release trigger (Top handle) and allow blade to come to a complete stop.

STEP 2 - HAZARDOUS ENERGY SOURCES, MAGNITUDES & ISOLATION POINTS

Source #1: Electrical (120V AC)

Isolation Location: 120V wall receptacle.

Lockout Procedure: Unplug cord from wall and install Rotating Electrical Plug Lockout (from LoTo station by exit door).

STEP 3 - STORED / RESIDUAL ENERGY DISSIPATION

Wait for abrasive wheel to coast to a complete stop.

STEP 4 - ZERO-ENERGY VERIFICATION ('TRY' STEP)

Depress handle trigger to verify zero electrical energy.