STUDENT PROJECTS LABORATORY - 930 KINNEAR RD

STANDARD OPERATING PROCEDURE (SOP) | ASSET: FAC-01 | TAG: FAC-SAFETY-01

Safety Hub, LOTO Lock Center, High-Voltage Battery Bench & Paint/Prep Booth

Facility Zone: Zone 6: Facility & Infrastructure (FAC) | Supervisor: Max Wright (Sr. Instructional Lab Supervisor)

1. REQUIRED PERSONAL PROTECTIVE EQUIPMENT (PPE)

1. ANSI Z87.1 Safety Glasses (Required Throughout 930 Kinnear Rd Shop)
2. HV Battery Bench: Class 0 High-Voltage Insulated Gloves (>55-60V), Face Shield, No Metal Jewelry
3. Paint/Prep Booth: Organic Vapor / Particulate Respirator & Nitrile Gloves

2. PRIMARY OPERATIONAL HAZARDS

1. High-voltage DC arc flash and Li-Ion thermal runaway fire hazard
2. Paint/solvent vapor accumulation if booth exhaust filters are clogged

3. BEFORE OPERATION CHECKLIST

1. Verify LOTO locks, tags, hasps, and rotating plug lockouts are stocked in machine shop cage and welding room.
2. HV Battery Bench: Place insulating bench covers down, remove all jewelry/watches, and verify quarantine container availability per Student Motorsports Battery SOP.

4. DURING OPERATION SAFETY RULES

1. Maintain clear 36" access around all electrical panels, eyewash stations, and fire extinguishers.
2. Never work alone on high-voltage (>55-60V) battery systems.

5. AFTER USE & SHOWROOM CLEANUP

1. Return all LOTO devices to master board upon maintenance completion and log in shop portal.

EMERGENCY SHUTDOWN & INCIDENT PROTOCOL:

For thermal runaway or fire: Pull fire alarm, evacuate shop, call 911 / Campus Public Safety, and notify Max Wright immediately.