Packaging
Quality Inspection Standard

DOCUMENT NUMBER	VERSION	EFFECTIVE DATE
YS-ZZZX-007	A/0	21 March 2026

Responsible unit: Packaging team

Operator requirements: Operators must be trained and qualified, and must be proficient in packaging operations, appearance inspection, safety precautions and protective measures.

Pre-operation inspection

1. Check that the appearance of incoming workpieces meets the quality requirements.

Packaging requirements

1. Clean workpiece surfaces thoroughly. Surfaces, edges and corners must be free from stains, pressure marks, scratches and impact damage. Edge bands must be undamaged. Panel surfaces must not be repaired; any exceptional case requires confirmation by the team leader or production manager.
2. Handle workpieces gently during packaging. Do not place them directly on the floor.
3. Do not mix orders, omit items, pack the wrong items or miss barcode scans.
4. Packaging must provide the required protection. When the carton is shaken, there must be no obvious rattling and no movement of the products inside. Glass, mirrors and other fragile products require shock-protective packaging.
5. Apply sealing tape evenly, securely and in accordance with the packaging requirements.
6. Place packaged panels flat and stable, with even support. Do not leave them tilted.

Inspection and Release

Packaging

Packaging inspection

1. Check for mixed orders, incorrect or missing items and missed barcode scans.
2. Verify that the packaging meets the requirements. Shake the carton to check for obvious rattling or movement inside. Verify shock protection for glass, mirrors and other fragile products.
3. Check that sealing tape is flat, secure and correctly applied.
4. Check that panels are stable and evenly supported, with no tilting that could cause deformation.
5. Apply packaging barcode labels neatly. Do not fold warehouse-entry barcode labels.

Stacking and package protection

1. Arrange completed packages by order. Do not stack multiple order batches on the same pallet. Use support boards of the appropriate uniform size; keep packages stable, evenly supported and level to prevent deformation.
2. Keep all barcode labels facing outward and unobstructed for warehouse receiving and dispatch scans.

Process responsibility

1. This is an operational controlled document. The Manufacturing Center is responsible for implementation, inspection, training and guidance, and for collecting and resolving process issues.
2. If difficulties arise during implementation, notify Yuan Jun or Li Junhui at the Manufacturing Center promptly for revision or guidance.
3. If this document conflicts with the earlier version held in the back-office system, follow this document.

Document control

Prepared by / Date	Reviewed by / Date	Approved by / Date

Revision log: Version / Change description / Change date / Changed by

Department review / Countersignature: _____

Inspection Examples

Packaging / Acceptance and defect references



ACCEPTABLE

Correctly packed and labeled panels



ACCEPTABLE

Protective packaging



NONCONFORMING

Surface stains



NONCONFORMING

Mixed-order packaging

Inspection Examples

Packaging / Acceptance and defect references



NONCONFORMING

Defective edge banding



NONCONFORMING

Panel damage



NONCONFORMING

Packaging does not meet requirements



NONCONFORMING

Incorrect package stacking