


# GB300 v26.06 + fix — throughput comes from the kernel stack (PR #10/#12/#13), not from freeing HBM

The real win: the batch lever runs past v26.05's ceiling  
(v26.05 pre-registered this — bs128 was the int32 bug, not a plateau)



Ratio is a throughput no-op  
→ bounds the HBM fix's speed contribution at  $\approx 0$

