```
% Jesse Wynn HW2 ME 537 Robotics
clc
% clear all
close all
% clear imports
% Problem 2(g) from the hw printout
import +ETS3.*
% link lengths
a1 = 0.5;
a2 = 0.5;
a3 = 0.5;
a4 = 0.25;
a5 = 0.25;
a6 = 0.5;
% define joint min and max
joint_min = -1; % radians
joint_max = 1;
num positions = 5;
increment = (joint_max - joint_min)/num_positions;
count = 0;
% initialize variables to store data in
x = zeros(1000000, 1);
y = zeros(1000000, 1);
z = zeros(1000000, 1);
% initial joint angles (at the negative extreme
q0 = [-1, -1, -1, -1, -1, -1];
% this way doesn't work
E3 = Rz('q1') * Tz(a1) * Ry('q2') * Tx(a2) * Ry('q3') * Tx(a3) *
Rx('q4') * Tx(a4) * Rz('q5') * Tx(a5) * Rx('q6') * Tx(a6);
% so instead I'll use the mdl_puma560 and edit it to match...
%p560.plot(q0)
% step through incremental joint angles to approximate the reachable
space
% set q = q0
q = q0;
% loop through first joint
for i = 0:num positions
    q(1) = q(1) + increment;
```

```
% loop through second joint
    for j = 0:num positions
        q(2) = q(2) + increment;
        % loop through third joint
        for k = 0:num_positions
            q(3) = q(3) + increment;
            % loop through fourth joint
            for 1 = 0:num_positions
                if 1 == 0
                    q(4) = q(4);
                else
                    q(4) = q(4) + increment;
                end
                % loop through 5th joint
                for m = 0:num_positions
                    if m == 0
                        q(5) = q(5);
                    else
                        q(5) = q(5) + increment;
                    end
응
                      disp(q(5))
                    % sixth joint is just twisting about the same axis
as 5
                    % so we won't add another loop
                    % figure out where the endefector is using fkine
                    T = p560.fkine(q);
                    x_pos = T.t(1);
                    y pos = T.t(2);
                    z_pos = T.t(3);
                    % increment the counter
                    count = count + 1;
                    % add the positions onto growing x vectors
                    x(count) = x_pos;
                    y(count) = y_pos;
                    z(count) = z_pos;
                      p560.plot(q)
%
응
                      disp(count)
                    % reset q(5)
                    if q(5) == joint_max
                        q(5) = joint_min;
                    end
```


```
end
                % reset q(4)
                if q(4) == joint_max
                    q(4) = joint_min;
                end
            end
            % reset q(3)
            if q(3) == joint_max
                q(3) = joint_min;
            end
        end
        % reset q(2)
        if q(2) == joint_max
            q(2) = joint_min;
        end
    end
    % reset q(1)
    if q(1) == joint_max
        q(1) = joint_min;
    end
end
% plots
% get the data that you want to plot
x_plot = x(1:count);
y_plot = y(1:count);
z_plot = z(1:count);
figure(1)
plot3(x_plot, y_plot, z_plot,'.')
hold on
xlabel('x position (m)')
ylabel('y position (m)')
zlabel('z position (m)')
title('Robot reachable workspace')
% p560.plot([0, 0, 0, 0, 0, 0])
p560.plot(q)
figure(2)
plot(x_plot, y_plot,'.')
xlabel('x position (m)')
ylabel('y position (m)')
title('Robot reachable workspace xy plane')
figure(3)
plot(x_plot, z_plot,'.')
xlabel('x position (m)')
zlabel('z position (m)')
title('Robot reachable workspace xz plane')
```


```
figure(4)
plot(y_plot, z_plot,'.')
ylabel('y position (m)')
zlabel('z position (m)')
title('Robot reachable workspace yz plane')
```


Warning: floor tiles too small, making them 2.000000 x bigger - change the size


or disable them

Warning: arrow option requires arrow3 from FileExchange









Published with MATLAB® R2017a