1. install arm toolchain sudo apt-get install gcc-arm-linux-gnueabi 2. 在boards.cfg中下面一行 pegmatite_config -Active arm armv7 pegmatite pegmatite 3. build u-boot make ARCH=arm CROSS_COMPILE=arm-linux-gnueabi- distclean make ARCH=arm CROSS_COMPILE=arm-linux-gnueabi- pegmatite_config 4. the step 3 builds the u-boot with "-O2 -fomit-frame-pointer" options, could not debug OPTFLAGS= -Os #-fomit-frame-pointer ==> OPTFLAGS=-00 build again